

Figure 1




Figure 2




Figure 3






Figure 4





TOZDAD" TSEBEBO





1


D9828351.O8O701














Figure 11b





Figure 12






Figure 14

389	MPTOM	Frequency	28	21	26		01	8		<u>-</u>	2	5 350	Close
387	list of the most likely causes for the specified SYMPTOM	Defect /	Defective Component	Test Error	Damaged	Broken Fiber	Pitted	Insufficient Solder	High Insertion loss	Excessive Solder	Proof Test Break	Wrong Component	
(2) Troubleshooting Guide	The following is a list of th	Defect Category /	Component Defects	Testing Defects	Component Defects	Fiber Defects	Connector Defects	Solder Defects	Testing Defects	Solder Defects	Testing Defects	Component Defects	

Figure 15